

ENERGIZER SELECTION GUIDE

Acres	Miles	Power	Joules	Squirrel	Raccoon	Horse	Cow	Pig	Sheep	Llama	Elk	Bear	Model
110V PLUG-IN													
Up to 30	Up to 10	Low Impedance	0.30	●	●	●							PW300
Up to 50	Up to 15	Low Impedance	0.50	●	●	●	●						PW500
Up to 75	Up to 20	Low Impedance	0.75			●	●	●					PW750
Up to 100	Up to 25	Low Impedance	1.0			●	●	●					PW1000
Up to 150	Up to 30	Ultra Low Impedance	1.50			●	●	●					PW1500
Up to 200	Up to 35	Ultra Low Impedance	2.0			●	●	●	●	●			PW2000
Up to 300	Up to 50	Ultra Low Impedance	3.0			●	●	●	●	●	●		PW3000
Up to 600	Up to 100	Ultra Low Impedance	6.0			●	●	●	●	●	●	●	PW6000
Up to 900	Up to 150	Ultra Low Impedance	9.0			●	●	●	●	●	●	●	PW9000
Up to 1,200	Up to 200	Ultra Low Impedance	12.0			●	●	●	●	●	●	●	PW12000
Up to 1,800	Up to 300	Ultra Low Impedance	18.0			●	●	●	●	●	●	●	PW18000
Up to 2,400	Up to 400	Ultra Low Impedance	24.0			●	●	●	●	●	●	●	FP24000XR
110V PLUG-IN /12V Battery													
Up to 100	Up to 25	Ultra Low Impedance	1.0			●	●	●	●	●	●		FP1000XD
Up to 300	Up to 50	Ultra Low Impedance	3.0			●	●	●	●	●	●	●	FP3000XD
12V BATTERY													
Up to 25	Up to 10	Low Impedance	0.25	●	●	●	●						PW250B
Up to 50	Up to 15	Low Impedance	0.50	●	●	●	●						PW500B
Up to 100	Up to 25	Ultra Low Impedance	1.0			●	●	●	●	●	●		PW1000B
Up to 200	Up to 35	Ultra Low Impedance	2.0			●	●	●	●	●	●	●	PW2000B
D-CELL /12V BATTERY													
Up to 35	Up to 15	Low Impedance	0.35	●	●	●	●	●	●	●	●	●	PW350B
Up to 35	Up to 15	Low Impedance	0.35	●	●	●	●	●	●	●	●	●	PW350B+
6V SOLAR													
Up to 3	Up to 3	Low Impedance	0.06	●	●	●	●						PW50S
12V SOLAR													
Up to 25	Up to 10	Ultra Low Impedance	0.15			●	●	●	●				PW100S
Up to 50	Up to 20	Ultra Low Impedance	0.25			●	●	●	●	●	●	●	PW200S
Up to 100	Up to 30	Ultra Low Impedance	0.50			●	●	●	●	●	●	●	PW500S



Available at:
UFA Farm & Ranch Supply stores



UFA.com



10375 State Route 43 | Streetsboro, Ohio 44241 USA

Phone: 330-562-2222 | Fax: 330-562-7403